# Transport Canada testing in support of the global technical regulation on Door Locks and Door Retention Components

Presentation to NHTSA Team Members

Simone Lalande
Standards and Regulations
Road Safety and Motor Vehicle Regulation

January 27, 2004

## **OUTLINE**

- Inertia Testing
- Latch Testing
- Combination Testing



## **INERTIA TESTING**





## Procedure

- 3 tests total as per gtr procedure:
  - 1 full vehicle test
  - 2 door-on-sled tests with 3 doors / test
- Hinged doors only
- Previously used in TC compliance programs
- Directions relative to
   VEHICLE axes, not LATCH / STRIKER axes



## Vehicles

• 1 full vehicle test



'00 Toyota Camry

2 door-on-sled tests with 3 doors / test









'98 Toyota Camry '03 Chevrolet TrailBlazer '02 Ford Focus


Vehicle	Door Direction	
Camry	All doors	Longitudinal Frontal



Vehicle	Door	Direction
TrailBlazer	Driver	Longitudinal Frontal
Focus	Hatchback	Lateral
Camry	Front Passenger	Lateral (Door Opening)



Vehicle	Door	Direction
TrailBlazer	Driver	Lateral (Door Opening)
Focus	Hatchback	Rear (Door Opening)
Camry	Front Passenger	Rollover (Towards Ground)



# Preparation of Full Vehicle Buck









# Preparation of Doors-on-Sled





**Orthogonal View** 

**Side View** 

# Preparation of Doors-on-Sled






**Orthogonal View** 

**Rotated View** 


# Measuring Door Opening

- 1 high-speed camera / door
- Low-resistance tape on full-vehicle doors



 Wires to determine primary + secondary latching

## Results - Sled Pulse




Vehicle	Door	Direction	Secondary Remained Latched	Primary Remained Latched	Notes
Camry	LF	Long. Frontal	$\checkmark$	<b>V</b>	
	LR	Long. Frontal	<b>√</b>	<b>√</b>	*
	RF	Long. Frontal	<b>√</b>	<b>√</b>	
	RR	Long. Frontal	<b>√</b>	<b>√</b>	*

- \* Tape broke on ALL doors, even though none opened
- Wires broke on rear doors, even though none opened










**Wires Intact** 

**Broken Tape** 





# Results - Wire Breaking



#### Post-test:

- 250 N load application: no door openings  $\sqrt{\phantom{a}}$
- Door opening, closing: all doors OK √
- Latch + striker inspection: no damage √
- Very little deformation of frame post-test  $\sqrt{\phantom{a}}$



Vehicle	Door	Direction	Secondary Remained Latched	Primary Remained Latched	Not es
TrailBlazer	Driver	Longitudinal Frontal	<b>√</b>	<b>√</b>	
Focus	Hatchback	Lateral	V	$\checkmark$	
Camry	Front Passenger	Lateral (Door Opening)	<b>√</b>	X	*


- Camry likely went to secondary latch, then rebounded into primary latch
- \* Camry door difficult to open and re-close post-test






**TrailBlazer** Focus






#### **Camry**



# Results - Wire Breaking



#### Post-test:

- 250 N load application: no door openings √
- Door opening, closing: all doors
   OK except Camry X
- Latch + striker inspection: minor damage to Camry latch X





Vehicle	Door	Direction	Secondary Remained Latched	Primary Remained Latched	Not es
TrailBlazer	Driver	Lateral (Door Opening)	<b>√</b>	X	*
Focus	Hatchback	Rear (Door Opening)	√	••	* *
Camry	Front Passenger	Rollover (Towards Ground)	<b>√</b>	<b>√</b>	

- TrailBlazer likely went to secondary latch, then rebounded into primary latch
- \* TrailBlazer door completely jammed, much deformation
- \*\* Difficult to tell whether Focus went to secondary latch




#### **TrailBlazer**





#### **Focus**






#### **Camry**



# Results - Wire Breaking



#### Post-test:


- 250 N load application: no door openings √
- Door opening, closing: all doors OK except TrailBlazer X
- Latch + striker
   inspection: major
   damage to Trailblazer
   door X



## Post-test Procedure

### Side hinged doors:

- -must drill hole without damaging internal linkages
- -handle "center" needs better definition




## Post-test Procedure

#### Rear hatchbacks:

-What to do about doors without handles?

-e.g. Opens with key, from inside only



## Conclusions - Results

- Failures = 0 / 10 tests
- Doors opening to secondary latched position =
  - (2 or 3) / 3 lateral or door opening direction
  - 0 / 6 longitudinal direction
  - 0 / 1 rollover direction
- Worst case = lateral or door opening direction
- More deformation than expected



## Conclusions - Procedure

- Tests feasible, more realistic than calculation
- Sled pulse initially difficult
- Monitoring door opening:
  - video absolutely necessary
  - tape method gives false results
  - wire method has potential

### Conclusions - Cost Breakdown

High cost for limited # of doors tested:

\$25,000 CAD for vehicle + door-on-sled prep.

- \$6,900 CAD for full vehicle prep.
- \$6,000 CAD x 3 doors = \$18,000 for door-on-sled prep.

\$20,000 CAD for sled testing

• \$6,600 per test x 3 tests



### Conclusions - Procedure

#### Full Vehicle

- Interaction with door trim
- Need many cameras

#### VS

#### **Door-on-Sled**

- Not testing door system
- Costly preparation
- Need expert machinist
- Difficult from compliance pt. of view



### Conclusions - Procedure

TC can provide input into more detailed + improved procedure, e.g.:

- Detailed drawings of bucks for full vehicle + door-on-sled tests
- Wire method
- Post-test procedure



# Conclusions - Canada's thoughts

- Limited information regarding inertia openings in the field
- Full-vehicle more realistic than door-inframe
- Tests expensive for information obtained
- Ideally, would like to do reconstructions of real-world inertia openings



# LATCH TESTING



# Objective

 What is max. load that latches can sustain?

Perspective on loads required by gtr tests


Selected latches




### Procedure

# As per CMVSS / FMVSS 206 procedure (SAE J839):

- Longitudinal, transverse directions
- Primary latch only (not secondary)





### Specimens

- 2003 MY vehicles
- Power locks
- High volume sales vehicles:

passenger car minivan

SUV pickup truck

(U.S. sales figures as of Oct 2003, Source: Automotive News)

 Latches, strikers, hardware: bought new from dealerships



# Results - Overview

Dir.	CMVSS / FMVSS
Long.	11,000 N 2473 lb.
Trans.	8,900 N 2000 lb.

#	Vehicle	Latch	Dir.	Maximum Load	
1	Ford	Driver	Long.	21,128 N <i>4750 lb</i> .	
	F-150	Driver	Trans.	19,669 N <i>4422 lb</i> .	
2	Toyota	Front	Long.	26,292 N 5911 lb.	
	Camry	Pass.		24,899 N 5598 lb.	
3	Dodge	Driver	Long.	29,948 N <i>6733 lb</i> .	
	Caravan		Trans.	17,143 N <i>3854 lb</i> .	
4	Chevrolet	Driver	Long.	42,981 N <i>9663 lb</i> .	
	Trail Blazer		Trans.	16,693 N <i>3753 lb</i> .	

### Results - Ford F-150


#### Longitudinal

Failure = 21,128 N (*4750 lb.*) Mode = striker bolts stripped

#### **Transverse**

Failure = 19,669 N (4422 lb.) Mode = 2 latch bolts failed





# Results - Toyota Camry

#### Longitudinal


Failure = 26,292 N (5911 lb.)

Mode = striker bolts stripped

#### **Transverse**

Failure = 24,899 N (5598 lb.)

Mode = striker failed at base






# Results - Dodge Caravan

#### Longitudinal


Failure = 29,948 N (6733 lb.)

Mode = striker failed at top



#### **Transverse**

Failure = 17,143 N (3854 lb.)
Mode = striker failed in 2
places



# Results - Chevy TrailBlazer

#### Longitudinal

Failure = 42,981 N (9663 lb.) Mode = striker failed in 2 places



#### **Transverse**

Failure = 16,693 N (3753 lb.)

Mode = latch opened



### **Summary - Maximum Loads**

Dir.	CMVSS / FMVSS
Long.	11,000 N
Trans.	8,900 N

Longitudinal loads

Transverse loads




### Summary - Failure Modes

- Longitudinal Failure Modes:
  - 4 / 4 related to striker
- Transverse Failure Modes:
  - 2 / 4 related to striker
  - 1 / 4 related to latch bolts
  - 1 / 4 related to latch opening



### **COMBINATION TESTING**



# Objective

- Evaluate test procedure, suggest improvements
- Obtain results for 4 latches
- Compare results to latch testing program results

### Procedure

- 4 tests total:
  - 2 tests as per gtr procedure in long. COMPRESSION
  - 2 tests in longitudinal TENSION
- Directions relative to
   LATCH / STRIKER axes, not VEHICLE axes
- Force application rate:
  - Longitudinal as per gtr (1.0 cm/min)
  - Lateral 0 6,650 N in 10 s (unspecified in gtr)




### **Test Matrix**


#	Vehicle	Latch	Longitudinal Force	
	vernicle		Direction	Load
1	Ford F-150	Driver	Compression	16,000 N
2	Toyota Camry	Front Pass.	Compression	16,000 N
3	Dodge Caravan	Driver	Tension	16,000 N
4	Chevrolet Trail Blazer	Driver	Tension	16,000 N





# Test Setup



# Test Setup








e.g. CAMRY




 Interference between striker plate and latch-supporting plate

Tests results insignificant







### Results - Long. Tension

No failures

No damage to any parts



# Results - Long. Tension

e.g. TRAILBLAZER



### Conclusions

- Tests are feasible (both compression + tension)
- Challenging simultaneous force application
- TC can provide:
  - detailed drawings of test setup + latch support plates
  - input into more detailed + improved procedure



### Conclusions

- TC does not recommend the longitudinal compression test using the current test procedure: not testing latch performance, testing fixture
- Difficult to simulate offset frontal crash forces using only latch
- Longitudinal tension test has potential, BUT:
  - research needed into lateral + longitudinal forces during actual offset collisions
  - is this realistic of UNSTRUCK side?

