

CRS-23-04

# German Position i-size ready car

# Problem

- Requirements for car manufacturer to support
  - RF (R2) and FF (F2X)
    - space for R2 not available in all cars for 2 seating positions
  - TT and support leg
    - support leg
      - geometry
      - floor integrity
  - ISOFIX universal

# Possible Solutions

- i-size ready car must offer all ISOFIX positions as i-size ready
- i-size ready car must
  - offer all ISOFIX positions as FF i-size ready
  - offer at least one ISOFIX position as i-size ready

# i-size ready at all ISOFIX positions

- Risk exists that the number of i-size ready vehicles will be very limited (this concerns also small family cars)

# i-size FF

- One label for all ISOFIX seating positions
- Customer tests which position can accept RF
- Customer can check in user manual which positions are able to accept RF

# i-size ready RF

- For i-size ready RF no requirements concerning front seat adjustment shall be applicable